

Client: Scottish Fire Service

Facility: Liberton Firestation

Report Date: 30/03/2014

Roof Section: Flat Roof

Report Data

Title Final Inspection

Notes: Contractor on site: Ronald Graham Roofing Ltd

Operatives on site: 5

Weather conditions: 7 degrees and overcast

Time of inspection: 9:45 am

A final inspection was carried out to the completed roofing works at Liberton Firestation. This was to ensure the Garland felt was in good condition and properly installed. I can confirm that we are happy with the completed roofing works, and the level of workmanship throughout the contract. This is evident when on the roof, with well sealed felt laps showing a bitumen bleed out. The gutter, perimeter and upstand details have been neatly installed and the laps well waterproofed. Garland are now happy to issue the warranty for the roof and a hardy copy will be sent to the client via post.



Overview of completed works.



Completed flat area with internal gutter detail.



Welting drip detail completed to perimeter edge.



Neat and tidy detailing work to vent pipes.



Perimeter and upstand details are well sealed, with a 5mm bead of bitumen extruding out of the laps.